

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA1183GL

*This certificate, issued to* National Aircraft Service, Inc.  
4332 Macon Road  
Tecumseh, MI 49286

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.* (See Type Certificate Data Sheet A10SW for complete certification basis).

*Original Product — Type Certificate Number:* A10SW

*Make:* Mitsubishi

*Model:* MU-2B-25, -26, -26A, -35, -36A, -40, -60

*Description of Type Design Change:*

Replace left side cockpit window with Crew Door conforming to National Aircraft Service Drawing List NA-DL1, Rev. D, dated April 7, 1987; and installed in accordance with Installation Instructions NAD-MU2-1, Rev. C, dated May 28, 1987.

*Limitations and Conditions:*

The compatibility of this modification with other previously approved modifications must be determined by the installer. FAA-approved National Aircraft Service Airplane Flight Manual Supplement, Rev. 1, dated April 21, 1987 is required.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*


*Date of application:* April 8, 1987

*Date reissued:*

*Date of issuance:* May 28, 1987

*Date amended:*



*By*   
W. F. Horn (Signature)

Manager, Chicago Aircraft Certification Office,  
ACE-115C, Central Region, FAA

(Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*