

Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate

Number SA85CH

certificate, issued to National Aircraft Service, Inc.
9133 Tecumseh-Clinton Road
Tecumseh, MI 49286

*ifies that the change in the type design for the following product with the limitations and conditions
for as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air*

*ulations. (See Type Certificate Data Sheet A10SW for Complete
Certification Basis.)*

inal Product—Type Certificate Number: A10SW

Make: Mitsubishi

Model: MU-2B-25, -26, -26A, -35, -36, -36A,
-40, -60

cription of Type Design Change:

ice Cabin Door Seal with National Aircraft Service Inc. Door Seal,
IADS01, Rev. A, dated 7-1-92 or later FAA-approved revisions,
illed in accordance with National Aircraft Service, Inc. Document
IU2-6, Rev. A, dated 7-1-92 or later FAA-approved revision.

itations and Conditions:

approval should not be extended to other aircraft of this model on
other previously approved modifications are incorporated, unless it
etermined by the installer that the interrelationship between this
ge and any of those other previously approved modifications will
duce no adverse effect upon the airworthiness of that aircraft.

*certificate and the supporting data which is the basis for approval shall remain in effect until sur-
dered, suspended, revoked, or a termination date is otherwise established by the Administrator of the
ral Aviation Administration.*

of application: March 6, 1990

Date reissued:

of issuance: July 8, 1993

Date amended:



By direction of the Administrator

Charles L. Smalley
(Signature)

for Donald P. Michal, Manager
Chicago Aircraft Certification Office

(Title)

alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47