

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA1703GL

*This certificate, issued to*

National Aircraft Service, Inc.  
4332 Macon Road  
Tecumseh, MI 49286

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4b of the Civil Air Regulations.*

(See Type Certificate Data Sheet 4A25 for complete  
Original Product — ~~type certificate number~~ certification basis). 4A25

*Make:* McDonnell Douglas  
*Model:*

Cargo Configured DC-8 Models Per Page 3  
this STC.)

*Description of Type Design Change:*

Modify existing Cargo Door Assembly by incorporating a Window Doubler Assembly thereby converting Cargo Door from a no window configuration to a configuration having one window in accordance with National Aircraft Service, Inc. Drawing List NAWD-DL2, Rev. D dated 1/26/92 or later FAA approved revisions; and per National Aircraft Service, Inc. Installation Instructions NAWD-C8-2, Rev. C dated 1/26/92 or later FAA approved revisions.  
*Limitations and Conditions:*

This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft.  
*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* March 14, 1991

*Date issued:*

*Date of issuance:* February 21, 1992

*Date amended:*



*By direction of the Administrator*

*(Signature)*

Donald P. Michal, Manager  
Chicago Aircraft Certification Office

*(Title)*

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America

# Supplemental Type Certificate

Number SA1703GL

**C** FAA AC 92.03578